





ASSEMBLY INSTRUCTION

Ax1 	Bx1 	Cx2 	Dx1 	Ex1 	Fx5 	Gx1 	Hx1 
Ix6  M6x30mm	Jx4  M8x40mm	Kx2  M8x20mm	Lx10  M6x16mm	Mx4  M6x20mm	W x4  M6x25mm	Vx1  M5x12mm	Rx5 
Nx1 	Ox1 	Px4 	Sx1 	Tx1 	Ux2 	Qx1 	


1




4




2




5




3



6




7



8

★ **Note: After all wires are connected, plug in the power supply.**



9

